

**Met One Instruments, Inc. has seen a number of failures of the barometric pressure sensor in the early models of the E-BAM. Manufacturing has changed a process to improve the reliability of this device.**

**The new process has been incorporated on all units leaving the factory since 31MAR05. All units, which have come to the factory for upgrades or repairs since this date, have also gotten the upgrade as a standard procedure.**

**This failure can cause different symptoms and can flag errors such as “Internal Communication Down”, “Delta Pressure/Vacuum Failed”, or “Pressure Test Failed”. The errors are usually intermittent.**

**If you are experiencing any of these failures, please call the factory at 541-471-7111 and ask for the Service Department to determine if your Instrument can benefit from this upgrade. There is no charge to perform this upgrade and we can usually perform the work in 5 business days.**

**Mike Putnam**  
**Service Supervisor**  
[service@metone.com](mailto:service@metone.com)  
**Ph. 541-471-7111 ext. 133**  
**Fax 541-471-7116**



**Met One Instruments, Inc.**

Corporate Sales & Service: 1600 Washington Blvd., Grants Pass, OR 97526, Phone: 1(541)471-7111, FAX: 1(541)471-7116  
Regional Service: 3206 Main Street, Suite 106, Rowlett, TX 75088, Phone: 1(972)412-4747, FAX: 1(972)412-4716  
Website: [www.metone.com](http://www.metone.com) Email: [service@metone.com](mailto:service@metone.com)

---